



What is the Treo 680 Product Update for AT&T?

The Palm Treo™ 680 Product Update for AT&T offers these significant improvements for your device:




- Improved power management for better battery life.
- Helps fix device "freezing" that may occur under certain conditions.
- Provides better support for networks unique to some Caribbean, Latin American, and Asian countries.
- Helps correct distorted characters that can occur in the title bar of the Phone application.
- Support for the new Daylight Saving Time legislation (available previously as a standalone update).
- Camera update for improved battery life (available previously as a standalone update).
- System Lockout improvement helps increase security.
- Updates Cingular branding, replacing it with the new AT&T branding.

Do I need to install the latest update?

- Press the  (phone) button
- Press the  (menu) button
- Select the 'Options' menu
- Select the 'Phone Info' option

If the *Software* field reads Treo680-1.09-ATT then the device has the latest software. If version is 1.03-CNG, 1.03-ATT or 1.08-ATT then install this update. If the software version ends with ROW then this update cannot be installed on your Treo™.



Where can I get the latest update?

This Product Update is available as a free download from the Palm website at <http://palm.com/680CriticalUpdate>. The software should be installed by all customers who purchased a Treo 680 for Cingular/AT&T before June 1, 2007.